DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-002158 Address: 333 Burma Road **Date Inspected:** 03-May-2008

City: Oakland, CA 94607

Project Name: SAS Superstructure OSM Arrival Time: 1500 **OSM Departure Time:** 100 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

CWI Name: CWI Present: Yes N/A No Yes N/A **Rod Oven in Use:** Yes **Inspected CWI report:** No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** Tower skin plate & OBG Deck Panels

Summary of Items Observed:

The Caltrans QA Inspector performed Magnetic Particle Testing (MT) verification of the QC MT Inspected and accepted welds. QA Inspector's MT verification appears to be acceptable with AWS D1.5-02 section 6.26.2.1 & 6. 26.2.3 Reference QA Magnetic Particle Test Report TL-6028 dated 5-3-08 for specific test data.

The Caltrans QA Inspector performed Ultrasonic Testing (UT) verification of the QC UT Inspected and accepted QA Inspector's visual and UT verification appears to be acceptable with AWS D1.5-02 section 6, table 6. 3. Reference QA Ultrasonic Test Report TL-6027 dated 5/3/08 for specific test data.

Summary of Conversations:

None noted.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Kelsey, David **Inspected By:** Quality Assurance Inspector **Reviewed By:** Cuellar, Robert **QA** Reviewer